

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9805050225      DOC. DATE: 98/04/30      NOTARIZED: NO      DOCKET #  
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina      05000400  
 AUTH. NAME      AUTHOR AFFILIATION  
 ROBINSON, W.R.      Carolina Power & Light Co.  
 RECIP. NAME      RECIPIENT AFFILIATION  
                          Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 98-002-01, per 10CFR50.73. Revised LER describes change in planned corrective actions for SSPS testing deficiency.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 213  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.


NOTES: Application for permit renewal filed. 05000400

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 PD	1 1	FLANDERS, S	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	<del>FILE CENTER</del>	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS  
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

A04



Carolina Power & Light Company  
PO Box 165  
New Hill NC 27562

William R. Robinson  
Vice President  
Harris Nuclear Plant

APR 30 1998

U.S. Nuclear Regulatory Commission  
ATTN: NRC Document Control Desk  
Washington, DC 20555

Serial: HNP-98-067  
10CFR50.73

SHEARON HARRIS NUCLEAR POWER PLANT UNIT 1  
DOCKET NO. 50-400  
LICENSE NO. NPF-63  
LICENSEE EVENT REPORT 98-002-01

Sir or Madam:

In accordance with 10CFR50.73, the enclosed revision to Licensee Event Report (LER) 98-002 is submitted. This revision describes a change in planned corrective actions for the Solid State Protection System testing deficiency.

Sincerely,

MV

Enclosure

c: Mr. J. B. Brady (HNP Senior NRC Resident)  
Mr. L. A. Reyes (NRC Regional Administrator, Region II)  
Mr. S. C. Flanders (NRC - NRR Project Manager)

9805050225 980430  
PDR ADOCK 05000400  
S PDR

U. S. Nuclear Regulatory Commission  
Document Control Desk / HNP-98-067  
Page 2 of 2

bcc: Ms. D. B. Alexander  
Mr. R. W. Baylor  
Mr. T. C. Bell  
Mr. H. K. Chernoff (RNP)  
Mr. B. H. Clark  
Mr. W. F. Conway  
Mr. G. W. Davis  
Mr. W. J. Dorman (BNP)  
Ms. J. P. Gawron (BNP)  
Mr. H. W. Habermeyer  
Mr. K. N. Harris  
Mr. W. J. Hindman  
Ms. C. W. Hobbs (HEEC)  
Mr. W. D. Johnson  
Mr. R. M. Krich  
Mr. M. B. Keef (HEEC)  
Ms. W. C. Langston  
Mr. C. W. Martin (BNP)  
Mr. R. D. Martin  
Mr. J. W. McKay  
Mr. B. A. Meyer  
Mr. P. M. Odom (RNP)  
Mr. W. R. Robinson  
Mr. R. F. Saunders  
Mr. F. E. Strehle  
Mr. J. M. Taylor  
Mr. D. L. Tibbitts  
Mr. C. A. VanDenburgh  
Mr. R. L. Warden (RNP)  
HNP Real Time Training  
INPO  
Harris Licensing File  
Nuclear Records