

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

New World Environmental, Inc.
448 Commerce Way
Livermore, California

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

REPORT NO.: 030-36174/2017-001

3. DOCKET NUMBER

030-36174

4. LICENSE NUMBER

04-27745-01

5. DATE(S) OF INSPECTION

November 16, 2017

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



1. Based on the inspection findings, no violations were identified.



2. Previous violation(s) closed.



3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.



Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):



4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Jason Dykert, Health Physicist	<i>Jason Dykert</i>	11-29-2017
BRANCH CHIEF	<i>Anthony Proch for M. Hay</i>	<i>Janine F Katonic</i>	<i>1/12/18</i>



Non-Public



Sensitive - Security-Related



Public



Non-Sensitive

Dykert, Jason

From: Dykert, Jason
Sent: Wednesday, November 29, 2017 1:39 PM
To: 'don@nwenvironmentalinc.com'
Subject: NRC inspection report 030-36174/2017-001
Attachments: IR 2017-001.pdf; NRC 314.pdf

Don,

Thanks for the documentation. I have attached a clear inspection report for your records, as we discussed. I have also attached NRC form 314 for license termination, if you should choose to close the license out.

There is a requirement, in 10 CFR 30.36(d)(3), that if no principle activities have been conducted within two years, that you notify the NRC and let us know of your intent to close out the license or ask for an extension. Because you have been applying for decommissioning work at SONGS, which is essential to achieving the purpose for which the license was issued, it appears you have conducted principle activities in the past two years.

Let me know if you have any other questions, just shoot me an email.

Jason Dykert