



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
1600 EAST LAMAR BOULEVARD
ARLINGTON, TEXAS 76011-4511

January 22, 2018

Mr. Mark E. Reddemann
Chief Executive Officer
Energy Northwest
MD 1023
P.O. Box 968
Richland, WA 99352

SUBJECT: COLUMBIA GENERATING STATION – NRC SECURITY INSPECTION
REPORT 05000397/2017410

Dear Reddemann:

On December 14, 2017, the U.S. Nuclear Regulatory Commission (NRC) completed a security inspection at your Columbia Generating Station, and the NRC inspector discussed the results of this inspection with Mr. W. Hettel, Vice President, Operations, and other members of your staff. The results of this inspection are documented in the enclosed inspection report.

The NRC inspector did not identify any finding or violation of more than minor significance.

This letter will be made available for public inspection and copying at <http://www.nrc.gov/reading-rm/adams.html> and at the NRC Public Document Room in accordance with 10 CFR 2.390, "Public Inspections, Exemptions, Requests for Withholding."

However, the enclosed report contains Security-Related Information, so the enclosed report will not be made publically available in accordance with 10 CFR 2.390(d)(1). If you choose to provide a response that contains Security-Related Information, please mark your entire response "Security-Related Information–Withhold from public disclosure under 10 CFR 2.390" in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in

<p>Enclosure transmitted herewith contains SUNSI. When separated from enclosure, this transmittal document is decontrolled.</p>

M. Reddemann

2

10 CFR 2.390(b)(1). The NRC is waiving the affidavit requirements for your response in accordance with 10 CFR 2.390(b)(1)(ii).

Sincerely,

/RA/

Jeremy R. Groom, Chief
Plant Support Branch 1
Division of Reactor Safety

Docket No. 50-397
License No. NPF-21

Enclosure:
Inspection Report 05000397/2017410
w/Attachment: Supplemental Information

cc w/o encl.: Electronic Distribution

M. Reddemann

3

COLUMBIA GENERATING STATION – NRC SECURITY INSPECTION
REPORT 05000397/2017410 – January 22, 2018

Distribution w/enclosure:

EWharton, NSIR
NSimonian, NSIR
CJohnson, NSIR
DGarner, NSIR
DHuyck, NSIR
RMcKinley, RI DRS
BDesai, RII DRS
SOrth, RIII DRS
KKennedy, ORA
SMorris, ORA
TPruett, DRP
RLantz, DRP
AVegel, DRS
JClark, DRS
JGroom, DRS
MHaire, DRP
RAlexander, DRP
DLackey, DRP
GKolcum, DRP
LBrandt, DRP
MBennett, DRP

Distribution w/o enclosure:

VDricks, ORA
JKlos, NRR
THipschman, DRS
MHerrera, FRMB
SKirkwood, RC
EUribe, DRS
JWeil, RIV/CAO
AMoreno, RIV/CAO
JBowen, RIV/OEDO
ACES
GWalker, OI
BMaier, ORA
RidsOeMailCenter Resource

DOCUMENT NAME: R:_REACTORS\COL\2017\CGS2017410-LTR-NonSGI-jlb.docx

ADAMS ACCESSION NUMBER: ML18022A089

Entire Report: ADAMS: ☒ Non-Publicly Available ☐ Non-Sensitive Keyword:
☒ SUNSI Review By: JLB ☒ Yes ☐ No ☐ Publicly Available ☒ Sensitive MD 3.4 A.3

ADAMS ACCESSION NUMBER: ML18022A094

Cover Letter Only: ADAMS: ☐ Non-Publicly Available ☒ Non-Sensitive Keyword:
☒ SUNSI Review By: JLB ☒ Yes ☐ No ☒ Publicly Available ☐ Sensitive NRC-002

OFFICE	PSI:PSB1	PSI:PSB1	C:PSB1	C:PB1	C:PSB1	
NAME	JBuchanan	AMeyen	JGroom	MHaire	JGroom	
SIGNATURE	/RA/	/RA/	/RA/	/RA/	/RA/	
DATE	1/16/18	1/16/18	1/17/18	1/19/18	1/22/18	

OFFICIAL RECORD COPY