

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	I	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4			5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0 1 7 8
REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
DOCKET NUMBER 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
EVENT DATE 69 70 71 72 73 74 75 76 77 78 79 80
REPORT DATE 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During steady state operations, personnel performing instrument sur-
0 3 | veillance tests were unable to zero #11 Side APRM Flow Converter. The
0 4 | error in flow indication was in the conservative direction and all trip
0 5 | points were operable. The faulty converter unit was replaced by a new
0 6 | unit and the problem was eliminated. This event had no safety implica-
0 7 | tions.
0 8 |
7 8 9 | 80

09		SYSTEM CODE IA		11	CAUSE CODE E		12	CAUSE SUBCODE G		13	COMPONENT CODE INSTRU					14	COMP. SUBCODE		15	VALVE SUBCODE Z		16								
7	8	9	10		11		12	13							18		19			20										
17		LER/RO REPORT NUMBER		EVENT YEAR 79		21	22	SEQUENTIAL REPORT NO. 025		24	25	26	OCCURRENCE CODE 03		28	29	REPORT TYPE L		30	31	REVISION NO. 0		32							
ACTION TAKEN C		18	FUTURE ACTION Z		19	EFFECT ON PLANT Z		20	SHUTDOWN METHOD Z		21	HOURS 000		22	ATTACHMENT SUBMITTED N		23	NPRD-4 FORM SUB. N		24	PRIME COMP. SUPPLIER N		25	COMPONENT MANUFACTURER G080		26				
23			34			35			36			37				40		41			42			43			44			47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Technicians were unable to zero APRM flow converter unit due to compo-

1 1 nent failure. The entire unit was replaced and the problem was elim-

1 2 inated.

1 3

1 4

7 8 9 80

8 9
FACILITY STATUS (28) % POWER (30) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)
1 5 E 0 9 6 NA B Instrument Surveillance Test
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
1 6 Z Z NA NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
1 7 0 0 0 Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
PERSONNEL INJURIES NUMBER DESCRIPTION
1 8 0 0 0 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
1 9 Z NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
PUBLICITY ISSUED DESCRIPTION
2 0 1 NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
7911300 48.4 S NRC USE ONLY

NAME OF PREPARER E. Duda

PHONE: (315) 343-2110 Ext 1558

