

NPDES NONCOMPLIANCE NOTIFICATION
Possible Noncompliance With Daily Average/Maximum Limitation
December 5, 1979

Plant: Palisades

Permit No MI-0001457

Outfall Description: Turbine Sump Oil Separator

Outfall No 800218

Parameter: Oil/Grease

Parameter No 00556

1. Date of Incident: 10-15, 23, 29-79
2. Identification of specific effluent limitation exceeded:
Daily maximum limitation of 20 mg/l for oil and grease.
3. Description of Incident:

<u>Date</u>	<u>Oil/Grease (Mg/l)</u>	<u>Volume (Gallons)</u>
10/15/79	41	9,000
10/23/79	29	5,000
10/29/79	24.1	3,000

4. Apparent Cause:

The problem was apparently caused by failure of the oil separator or improper operation.

5. If not immediately corrected, the anticipated time the condition is expected to continue:

NA

6. Corrective Action - The following corrective action was taken or will be taken to reduce, eliminate and prevent recurrence:

The separator was restored to proper operation and subsequent analysis shows results in the 1-10 mg/l range after 11/1/79.

7. Additional Comments:

NA

8. Signed: R L Fobes

Ronald L Fobes