

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	8	0	7	1	1	0	7	7	8	8	1	1	2	9	7	8	9		
50	61	DOCKET NUMBER										63	69	EVENT DATE					74	75	REPORT DATE					80

On 11/7/78, while searching in station records for other information, a Procedure

there were no consequences. The health and safety of the public were not affected.

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

review and approved.

PUBLICITY
ISSUED DESCRIPTION (45) 7812050211 NRC USE ONLY
2 0 N (44) NA
7 8 9 10 58 69 80

NRC USE ONLY

58 69

(804) 357-3184

PHONE:

Surry Power Station, Unit #1
Docket No: 50-280
Report No: 78-037/03L-0
Event Date: 11/7/78

Late Review of Procedure Deviation

1. Description of Event:

On 11/7/78, while searching in station records for information concerning reactor coolant pump motors, a Procedure Deviation to OP-5.1, Filling and Venting the Reactor Coolant System, dated 1/15/77 was found unreviewed by the Station Nuclear Safety and Operating Committee. Since the deviation was not reviewed within the prescribed time frame as stated in T.S. 6.4.E, this event is reportable per T.S. 6.6.2.b.(3).

2. Probable Consequence of Event:

Since the deviation involved temporary changes to the procedure but did not change the intent of the original procedure and since the deviation was approved by the Shift Supervisor prior to implementation, there were no consequences from this event. Therefore, the health and safety of the public were not affected.

3. Cause of Event:

The procedure deviation was misrouted to the records vault with the completed procedure without being reviewed by SNSOC.

4. Immediate Corrective Action:

Upon discovery of the deviation, it was forwarded to SNSOC for review at the 11/8/78 SNSOC meeting.

5. Scheduled Corrective Action:

None required.

6. Action Taken to Prevent Recurrence:

Since this was a random event and this is not a recurring problem, no action is required.

7. Generic Implications:

Since this is not a recurring problem, there are no generic implications.