

CENTRAL FILES

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

May 29, 1979

79 MAY 31 A 9:13

USNRC REGION I  
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Serial No. 418  
PO/DLB:baw  
Docket Nos: 50-280  
50-281  
50-338  
50-339

SUBJECT: IE BULLETIN 78-12, 12A, AND 12B  
SURRY POWER STATION UNIT NOS. 1 AND 2  
NORTH ANNA POWER STATION UNIT NOS. 1 AND 2

Dear Mr. O'Reilly:

This is in response to IE Bulletin 78-12, 12A, and 12B, "Atypical Weld Material in Reactor Pressure Vessel Welds", which requests information on reactor vessel welds for Surry Power Station Unit Nos. 1 and 2 and North Anna Power Station Unit Nos. 1 and 2. We have made arrangements through our NSSS vendor for the retrieval of this information. Based on estimates provided by our NSSS vendor, the information requested should be forwarded to you by approximately September 1, 1979.

Very truly yours,

*C. M. Stallings*

C. M. Stallings  
Vice President-Power Supply  
and Production Operations

cc: U. S. NRC  
Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
Washington, D. C. 20555

CCP

002

7907180145

790295  
OFFICIAL COPY