

E 05/10/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)  
DISTRIBUTION FOR INCOMING MATERIAL

50-335

REC: OREILLY J P  
NRC

ORG: SCHMIDT A D  
FL PWR & LIGHT

DOCDATE: 04/25/78  
DATE RCVD: 05/09/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT: LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-335/78-010) ON 03/26/78 CONCERNING ONE  
CHANNEL OF STEAM GENERATOR LOW PRESSURE MEASUREMENT FOR THE MAIN STEAM  
ISOLATION SIGNAL FAILED, REQUIRING ACTION IN ACCORDANCE WITH TECH SPEC  
3.3.2.1.B.

PLANT NAME: ST LUCIE #1

REVIEWER INITIAL: XJM  
DISTRIBUTOR INITIAL: ML

\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*

INCIDENT REPORTS  
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF REID\*\*W/4 ENCL

INTERNAL:

REG FILE\*\*W/ENCL  
I & E\*\*W/2 ENCL  
SCHROEDER/IPPOLITO\*\*W/ENCL  
NOVAK/CHECK\*\*W/ENCL  
KNIGHT\*\*W/ENCL  
HANAUER\*\*W/ENCL  
EISENHUT\*\*W/ENCL  
SHAO\*\*W/ENCL  
KREGER/J. COLLINS\*\*W/ENCL  
K SEYFRIT/IE\*\*W/ENCL

NRC PDR\*\*W/ENCL  
MIPC\*\*W/3 ENCL  
HOUSTON\*\*W/ENCL  
EEB\*\*W/ENCL  
BUTLER\*\*W/ENCL  
TEDESCO\*\*W/ENCL  
BAER\*\*W/ENCL  
VOLLMER/BUNCH\*\*W/ENCL  
ROSA\*\*W/ENCL

EXTERNAL:

LPDR/S  
FT PIERCE, FL\*\*W/ENCL  
TIC\*\*W/ENCL  
NSIC\*\*W/ENCL  
ACRS CAT B\*\*W/16 ENCL


COPIES NOT SUBMITTED PER  
REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 45 ENCL 45  
SIZE: 1P+1P


CONTROL NBR: 781300089

\*\*\*\*\* THE END \*\*\*\*\*

80  
4



REGULATORY DOCKET FILE COPY



FLORIDA POWER & LIGHT COMPANY

April 25, 1978  
PRN-LI-78-118

1978 MAY 9 AM 10 04  
RECEIVED DISTRIBUTION  
SERVICES UNIT  
US NRC  
DISTRIBUTION SERVICES  
BRANCH

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N.W., Suite 1217  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-10  
ST. LUCIE UNIT 1  
DATE OF OCCURRENCE: MARCH 26, 1978  
TECHNICAL SPECIFICATION 3.3.2.1.b  
STEAM GENERATOR PRESSURE-LOW

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

*JRBenson*  
for A. D. Schmidt  
Vice President  
Power Resources

MAS/mb

Attachment

cc: Harold F. Reis, Esquire  
Director, Office of Inspection and Enforcement. (30)  
Director, Office of Management Information and  
Program Control (3)

781300089

A002  
5/11

NOTED

10 MAY 68

RECEIVED

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME <span style="border: 1px solid black; padding: 2px;">01</span> <span style="border: 1px solid black; padding: 2px;">F</span> <span style="border: 1px solid black; padding: 2px;">L</span> <span style="border: 1px solid black; padding: 2px;">S</span> <span style="border: 1px solid black; padding: 2px;">L</span> <span style="border: 1px solid black; padding: 2px;">S</span> <span style="border: 1px solid black; padding: 2px;">1</span>	LICENSE NUMBER <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">-</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">-</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span>	LICENSE TYPE <span style="border: 1px solid black; padding: 2px;">4</span> <span style="border: 1px solid black; padding: 2px;">1</span> <span style="border: 1px solid black; padding: 2px;">1</span> <span style="border: 1px solid black; padding: 2px;">1</span> <span style="border: 1px solid black; padding: 2px;">1</span>	EVENT TYPE <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">3</span>
---	---	---	---

CATEGORY <span style="border: 1px solid black; padding: 2px;">01</span> CONT	REPORT TYPE <span style="border: 1px solid black; padding: 2px;">L</span>	REPORT SOURCE <span style="border: 1px solid black; padding: 2px;">L</span>	DOCKET NUMBER <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">5</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">-</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">3</span> <span style="border: 1px solid black; padding: 2px;">3</span> <span style="border: 1px solid black; padding: 2px;">5</span>	EVENT DATE <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">3</span> <span style="border: 1px solid black; padding: 2px;">2</span> <span style="border: 1px solid black; padding: 2px;">6</span> <span style="border: 1px solid black; padding: 2px;">7</span> <span style="border: 1px solid black; padding: 2px;">8</span>	REPORT DATE <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">4</span> <span style="border: 1px solid black; padding: 2px;">2</span> <span style="border: 1px solid black; padding: 2px;">5</span> <span style="border: 1px solid black; padding: 2px;">7</span> <span style="border: 1px solid black; padding: 2px;">8</span>
---	--	--	--	---	--

**EVENT DESCRIPTION**

02 One channel of steam generator low pressure measurement for the Main Steam Isolation

03 Signal failed, requiring ACTION in accordance with Specification 3.3.2.1.b The channel

04 was bypassed, repaired, and returned to service in 3 1/2 hours which is well within the

05 48-hour limit for bypass operation. (78-335-10).

06

SYSTEM CODE <span style="border: 1px solid black; padding: 2px;">07</span> <span style="border: 1px solid black; padding: 2px;">C</span> <span style="border: 1px solid black; padding: 2px;">D</span>	CAUSE CODE <span style="border: 1px solid black; padding: 2px;">E</span>	COMPONENT CODE <span style="border: 1px solid black; padding: 2px;">I</span> <span style="border: 1px solid black; padding: 2px;">N</span> <span style="border: 1px solid black; padding: 2px;">S</span> <span style="border: 1px solid black; padding: 2px;">T</span> <span style="border: 1px solid black; padding: 2px;">R</span> <span style="border: 1px solid black; padding: 2px;">U</span>	FRAME COMPONENT SUPPLIER <span style="border: 1px solid black; padding: 2px;">N</span>	COMPONENT MANUFACTURER <span style="border: 1px solid black; padding: 2px;">F</span> <span style="border: 1px solid black; padding: 2px;">3</span> <span style="border: 1px solid black; padding: 2px;">2</span> <span style="border: 1px solid black; padding: 2px;">4</span>	VIOLATION <span style="border: 1px solid black; padding: 2px;">N</span>
---	---	---	---	---	--

**CAUSE DESCRIPTION**

08 The power supply (Power Mate 15V, 300 ma DC) failed, apparently at the end of its

09 normal service life. It was replaced and the channel calibrated properly. This was

10 the first event of this type due to a failed power supply.

FACILITY STATUS <span style="border: 1px solid black; padding: 2px;">11</span> <span style="border: 1px solid black; padding: 2px;">E</span>	% POWER <span style="border: 1px solid black; padding: 2px;">1</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span>	OTHER STATUS N/A	METHOD OF DISCOVERY <span style="border: 1px solid black; padding: 2px;">a</span>	DISCOVERY DESCRIPTION N/A
---	--	---------------------	--	------------------------------

FORM OF ACTIVITY RELEASED <span style="border: 1px solid black; padding: 2px;">12</span> <span style="border: 1px solid black; padding: 2px;">Z</span>	CONTENT OF RELEASE <span style="border: 1px solid black; padding: 2px;">Z</span>	AMOUNT OF ACTIVITY N/A	LOCATION OF RELEASE N/A
---	---	---------------------------	----------------------------

**PERSONNEL EXPOSURES**

NUMBER <span style="border: 1px solid black; padding: 2px;">13</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span>	TYPE <span style="border: 1px solid black; padding: 2px;">Z</span>	DESCRIPTION N/A
--	---	--------------------

**PERSONNEL INJURIES**

NUMBER <span style="border: 1px solid black; padding: 2px;">14</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span> <span style="border: 1px solid black; padding: 2px;">0</span>	DESCRIPTION N/A
--	--------------------

**PROBABLE CONSEQUENCES**

15 N/A

**LOSS OR DAMAGE TO FACILITY**

TYPE <span style="border: 1px solid black; padding: 2px;">16</span> <span style="border: 1px solid black; padding: 2px;">Z</span>	DESCRIPTION N/A
--	--------------------

**PUBLICITY**

17 N/A

**ADDITIONAL FACTORS**

18 N/A

19 N/A

NAME: M. A. Schoppman

PHONE: 305-552-3802

Handwritten notes in the top right corner, possibly including a date and some illegible text.