

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

January 30, 1981

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
Attn: Mr. Steven A. Varga
Operating Reactors Branch No. 1
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Serial No. 051
NO/SPS:ms
Docket No. 50-280
License No. DPR-32

Dear Mr. Denton:

Enclosed herein, pursuant to the license conditions issued under Amendment No. 47 to the operating license for Surry Power Station Unit No. 1, is Radiological Progress Report No. 2 for the Steam Generator Repair Program (SGRP). This report describes the occupational exposure expended, the dose reduction techniques employed and their effectiveness, and the radioactive effluents and solid waste generated during the period November 1, 1980 through December 31, 1980.

If you have any questions on this matter, do not hesitate to contact us.

Very truly yours,



B. R. Sylvia
Manager - Nuclear
Operations and Maintenance

Enclosure

cc: Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region II

RECEIVED
NUCLEAR REGULATORY COMMISSION
JAN 31 1981

JAN 31 1981

JAN 31 1981

A001
5
11

R

8102020373