



FLORIDA POWER & LIGHT COMPANY

September 23, 1977  
L-77-301

*Central File*  
*50-335*  
*387*

Mr. James P. O'Reilly, Director, Region II,  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
230 Peachtree Street, N.W., Suite 1217  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: IE:II:JPO  
50-389  
50-335  
50-250  
50-251

We have reviewed IE Bulletin 77-03 and have determined that the subject solid state protection system is not installed or scheduled to be installed at St. Lucie Units 1 and 2 or Turkey Point Units 3 and 4.

Very truly yours;

*for J A. De Mistry*

Robert E. Uhrig  
Vice President

REU/WAK:ltm

cc: Robert Lowenstein, Esq.

*Ad*  
*6*