

A 07128/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL 50-316

REC: KEPPLER J G
NRC

ORG: SHALLER D V
IN & MI PWR

DOCDATE: 07/21/78
DATE RCVD: 07/26/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED

SUBJECT:

LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-316/78-019) ON 04/04/78 CONCERNING
DURING NORMAL OPERATION, ACCUMULATOR # 1, 2 AND 3 WERE FILLED...SAMPLING
SURVEILLANCE REQUIREMENTS OF TECH SPEC 4.5.1 WERE NOT MET WITHIN THE 6 HOUR
TIME LIMIT... W/ATT LER 78-023.

PLANT NAME: COOK - UNIT 2

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: M

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

NOTES:

1. SEND 3 COPIES OF ALL MATERIAL TO I&E
ED REEVES--1 CY ALL MATERIAL

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR-CHIEF ORB#1 BC**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL
1 & ~~E**W/3~~ ENCL
I & C SYSTEMS BR**W/ENCL
NOVAK/CHECK**W/ENCL
AD FOR ENG**W/ENCL
HANAUER**W/ENCL
AD FOR SYS & PROJ**W/ENCL
ENGINEERING BR**W/ENCL
KREGER/J. COLLINS**W/ENCL
K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL
MIPC**W/3 ENCL
EMERGENCY PLAN BR**W/ENCL
EEB**W/ENCL
PLANT SYSTEMS BR**W/ENCL
AD FOR PLANT SYSTEMS**W/ENCL
REACTOR SAFETY BR**W/ENCL
VOLLMER/BUNCH**W/ENCL
POWER SYS BR**W/ENCL

EXTERNAL:

LPDR'S
ST. JOSEPH, MI**W/ENCL
TIC, LIZ CARTER**W/ENCL
NSIC**W/ENCL
ACRS CAT B**W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P+2P

CONTROL NBR: 782010113

A0460

***** THE END *****



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

D. Lenham
FILE

July 21, 1978

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications
the following reports are submitted:

RO 78-019/03L-1
RO 78-023/03L-1.

Sincerely,


D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R. Kilburn
R.J. Vollen BPI
K.R. Baker RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
R.S. Keith
Dir., IE (30 copies)
Dir., IE (3 copies)

JUL 24 1978

AO 4
A002
5/11
GP



(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 0 4 0 4 7 8 8 0 7 2 1 7 8 9

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 9		SYSTEM CODE S F		CAUSE CODE A		CAUSE SUBCODE X		COMPONENT CODE Z Z Z Z Z				COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20		
LER/RO REPORT NUMBER 7 8		EVENT YEAR 7 8		SEQUENTIAL REPORT NO. 0 1 9		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 1					
ACTION TAKEN H		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N			
18		19		20		21		22		23		24			
PRIME COMP. SUPPLIER Z		COMPONENT MANUFACTURER Z 9 9 9													
25		26													

2	0	Z	(44)	NA
---	---	---	------	----

PHONE: 616-465-5901

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	0	4	0	8	7	8	8	0	7	2	1	7	8	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE I B 11		CAUSE CODE A 12		CAUSE SUBCODE C 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE X 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 7 8		EVENT YEAR 7 8		SEQUENTIAL REPORT NO. 0 2 3		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 1	
ACTION TAKEN G 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22		ATTACHMENT SUBMITTED Y 23	
NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER W 1 2 p 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
B										0 4 0										NA										A										ROUTINE REVIEW									
ACTIVITY CONTENT										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																													
RELEASED OF RELEASE										NA										NA																													

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	(40)
NA			

7	8	9	10	NRC USE ONLY	
ISSUED			DESCRIPTION	(45)	

NRC USE ONLY

[illegible]

PHONE: 616-465-5901

ATTACHMENT TO LICENSEE EVENT REPORT # 78-023/03L-1

Cause Description

THESE HAVE BEEN ADDED TO THE APPROPRIATE PROCEDURES AND FUNCTIONALLY TESTED. TO PREVENT RECURRENCE, ADMINISTRATIVE CONTROLS HAVE BEEN ESTABLISHED TO INSURE TEMPORARY CHANGES ARE APPROVED AND INCORPORATED INTO THE APPLICABLE PROCEDURES.