

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

MR. J. E. KEPPLER

FROM:

INDIANA & MICHIGAN POWER CO.
BRIDGMAN, MICHIGAN
R. W. JERGENSENDATE OF DOCUMENT
4/30/76DATE RECEIVED
5/6/76☒ LETTER☐ NOTORIZED

PHOP

INPUT FORM

NUMBER OF COPIES RECEIVED

☐ ORIGINAL
☒ COPY☒ UNCLASSIFIED

ONE SIGNED

DESCRIPTION

LTR. TRANS THE FOLLOWING:

ENCLOSURE

LICENSEE EVENT RPT. (RO 50-315/76-16) ON 4/1/76
CONCERNING A TUBE LEAK IN EMERGENCY DIESEL
GENERATOR ICD REAR BANK AIR AFTERCOOLER.

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME:

COOK # 1

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

SAFETY

FOR ACTION/INFORMATION

ENVIRO 5/7/76 RJL

☒ BRANCH CHIEF:

W/3 CYS FOR ACTION

KNEIL

☒ L.I.C. ASST:

W/7 CYS

SERVICE

ACRS 16 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

☒ REG FILE☒ NRC PDR☒ I & E (2)☒ MIPC (3)☒ SCHROEDER/IPPOLITO☒ HOUSTON☒ NOVAK/CHECK☒ GRIMES/SCHWENGER☒ CASE☒ E. WILLIAMS☒ HANAUER☒ TEDESCO/MACCARY☒ EISENHUT☒ BAER☒ SHAO☒ VOLLMER/BUNCH☒ KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

☒ T.P.D.R. ST. JOSEPH, M.I.☒ TIC☒ NSIC

CONTROL NUMBER

4536

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000




INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

April 30, 1976

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137




Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 4, Section 2.b, the following report is submitted:


RO 50-315/76-16.

Sincerely,


R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R. Kilburn
R.J. Vollen BPI
R.C. Callen MPSC
K.R. Baker RO: III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
PNSRC
R.S. Keith
Dir., IE (30 copies)
Dir., MIPC (3 copies)



Regulatory Docket File

4536

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER														LICENSE TYPE					EVENT TYPE	
01	M	I	D	C	C	I	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3										
7	8	9				14	15											25	26			30	31	32										
01		CONT		CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER								EVENT DATE				REPORT DATE												
7	8			57	58	59	60			0	5	0	-	0	3	1	5	0	4	0	1	7	6	0	4	3	0	7	6					

EVENT DESCRIPTION

02	Emergency Diesel Generator 1CD Rear Bank Air Aftercooler was discovered to have a tube																								80
03	leak. The cooler was replaced 4-6-76. Emergency Diesel Generator 1AB developed a																								80
04	similar leak in its rear bank air aftercooler. It was replaced 4-24-76.																								80
05																									80
06	(R0 50-315/76-16)																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	E	E	F	H	T	E	X	C	H	A	W	3	1	5	N
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	48

CAUSE DESCRIPTION

08	NA																								80
09																									80
10																									80

FACILITY STATUS		% POWER		OTHER STATUS				METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
11	E	0	9	0	N/A			b	Routine inspection						
7	8	9	10	11	12	13	14	44	45	46					80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE							
12	Z	Z	N/A					N/A							
7	8	9	10	11	12	13	14	44	45	46					80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	N/A
7	8	9	10	11	12

PERSONNEL INJURIES

NUMBER		DESCRIPTION	
14	0	0	0
7	8	9	10

OFFSITE CONSEQUENCES

15	N/A																								80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION	
16	Z	N/A	
7	8	9	10

PUBLICITY

17	N/A																								80
----	-----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18																									80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																									80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: David G. Wizner

PHONE: 616-465-5901