

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 9860

FILE: INCIDENT REPORT FILE

FROM: Indiana & Mich. Power Co. Bridgman, Mich. 49106 R.W. Jurgensen			DATE OF DOC 9-10-75	DATE REC'D 9-16-75	LTR XX	TWX	RPT	OTHER
TO: Mr. J.G. Keppler			ORIG 1 signed	CC	OTHER	SENT AEC PDR XX SENT LOCAL PDR XX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-315			

DESCRIPTION: Ltr trans the following:

ENCLOSURES: Licensee Event Report AO-50-315/75-52 on 8-11-75 re failure of reactor trip breakers was not met....

(1 cy encl rec'd)

ACKNOWLEDGED

PLANT NAME: Donadl C. Cook Unit 1

Do Not Remove

FOR ACTION/INFORMATION

DHL 9-18-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
✓ KNIEL (L) W/3 Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

REG FILE NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	TECH REVIEW SCHROEDER MACCARY KNIGHT PAWLICKI SHAO ** STELLO ** HOUSTON ** NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON ** GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC ASST R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) ✓ M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	A/T IND. BRAITMAN SALTZMAN MELTZ PLANS MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	---	---	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR St. Joseph, Mich.	1 - TIC (ABERNATHY) (1)(2)(10)	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - NSIC (BUCHANAN)	1 - W. PENNINGTON, Rm E-201 GT		1 - BROOKHAVEN NAT LAB
1 - ASLB	1 - CONSULTANTS		1 - G. ULRIKSON, ORNL
1 - Newton Anderson	NEWMARK/BLUME/AGBABIAN		1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
5 - ACRS SENT TO LIC ASST M. Service 9-18-75			1 - J. D. RUNKLES, Rm E-201 GT
** SEND ONLY TEN DAY REPORTS			

[Handwritten signature]

... ..
... ..
... ..

... ..

...

... ..

... ..
... ..
... ..

(... ..)


... ..

... ..

... ..

... ..

Regulatory Docket File



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106



September 10, 1975

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of Appendix A Technical Specifications and the United States Nuclear Regulatory Commission Regulatory Guide 1.16, Revision 3, Section 2.b, the following Abnormal Occurrence Report is submitted:


AO 50-315/75-52

Sincerely,


R.W. Jurgensen
Plant Manager

/bab

cc: R.S. Hunter
J.E. Dolan
G.E. Lien
R.J. Vollen BPI
R. Kilburn
R.C. Callen MPSC
K.R. Baker RO: III
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.
G. Olson
PNSRC
R.S. Keith
Director, IE (30 copies)
Director MIPC (3 copies)



9860

SEP 11 1975

40

LICENSEE EVENT REPORT Regulatory Docket File

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE
NAME

Received w/ Ltr Dated 9-10-75
LICENSE NUMBER

LICENSE
TYPE

EVENT
TYPE

01 MIDIC 1 00-000000-00 41111 01
7 8 9 14 15 25 26 30 31 32

01 CON'T P O L L 050-0315 0811175 090375
7 8 57 58 59 60 61 68 69 74 75 80

EVENT DESCRIPTION

02 WHILE IN MODE 1, AT 80 PERCENT POWER, INTERNAL AUDITING
03 REVEALED THAT TECHNICAL SPECIFICATIONS TABLE 4.3-1 NUMBER
04 21 REQUIREMENT FOR CHANNEL FUNCTIONAL TEST OF REACTOR TRIP
05 BREAKERS WAS NOT MET FOR APRIL, MAY AND JULY 1975.
06 (AO-50-315/75-52)

SYSTEM
CODE

CAUSE
CODE

COMPONENT CODE

PRIME
COMPONENT
SUPPLIER

COMPONENT
MANUFACTURER

VIOLATION

07 Z Z A Z Z Z Z Z Z Z Z Z Y
7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08 CAUSE WAS FAILURE TO INCLUDE THE MONTHLY TEST ON THE
09 SURVEILLANCE TEST SCHEDULE. THE SCHEDULE WAS REVISED TO
10 INCLUDE THIS TEST MONTHLY AND ALSO PRIOR TO START-UP.

FACILITY
STATUS

% POWER

OTHER STATUS

METHOD OF
DISCOVERY

DISCOVERY DESCRIPTION

11 E 080 NA B INTERNAL AUDITING
7 8 9 10 12 13 44 45 46 80

FORM OF
ACTIVITY
RELEASED

CONTENT
OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

12 Z Z NA NA
7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES

13 000 Z NA
7 8 9 11 12 13 80

PERSONNEL INJURIES

14 000 NA
7 8 9 11 12 80

OFFSITE CONSEQUENCES

15 NONE- TRIP BREAKERS TESTED SATISFACTORILY IN AUGUST
7 8 9 80

LOSS OR DAMAGE TO FACILITY

16 Z NA
7 8 9 10 80

PUBLICITY

17 NA
7 8 9 80

ADDITIONAL FACTORS

18 NA
7 8 9 80

19 NA
7 8 9 80

NAME: G. SWAN

PHONE: (616) 465-5901 (368)

10-10-52

10-10-52