



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
2443 WARRENVILLE RD. SUITE 210
LISLE, IL 60532-4352

SEP 05 2018

John P. Sutkowski, M.D.
Radiation Safety Officer
Deaconess Hospital
c/o Midwest Radiologic Imaging
4087 Gateway Blvd.
Newburgh, IN 47630

Dear Dr. Sutkowski:

Enclosed is Amendment No. 109 to your NRC Material License No. 13-00142-02 in accordance with your request.

This amendment adds a new location of use at 4007 Gateway Boulevard, Newburgh, Indiana to your license, concurrent with the termination of the NRC license for The Heart Group under license no. 13-24706-01.

This was done in accordance with the letter dated May 29, 2018, signed by Lynn Lingafelter, Chief Operating Officer for Deaconess Hospital, Inc., and Sridhar Banuru, M.D., Vice President for The Heart Group.

The termination for The Heart Group has been sent under separate cover to Dr. Banuru's attention.

Since licensed activities have continued at The Heart Group, it was directly merged into the license for Deaconess Hospital. No final status surveys were necessary due to licensed activities being conducted continuously while the amendment and termination requests were pending completion.

Please note that, in the course of conducting this review, we noted that no facility diagrams were submitted for The Heart Group location, in order for it to be added to the license. As an interim measure, we added the letter dated May 17, 2012, from The Heart Group license, condition no. 14.A., as it should have appeared, excluding reference to the location at 415 W. Columbia Street, Evansville, Indiana. This letter appears on condition no. 14.A. of Amendment No. 18 for license no. 13-24706-01 as "Application dated May 23, 2012," which was incorrect. It should have been identified as "the letter dated May 17, 2012."

Within 30 days of the date of this letter please submit current diagrams for the facilities at the Heart Group location that are prepared in accordance with NUREG 1556, Vol. 9, Rev. 2, section 8.16 and Figure 9.1, and adding the direction of north. The diagrams included in the letter dated May 17, 2012, for The Heart Group were only very minimally adequate and should be replaced by more appropriate and current diagrams at this time. Please do not send blueprints or copies

The enclosed documents contain sensitive security-related information.
When separated from this cover letter this letter is uncontrolled.

J. Sutkowski

- 2 -

or excerpts of blueprints as they typically show much of what we do not need and very little, if any, of what we do need.

Please address your response to my attention at the address above as "additional information to control number 609004." If an alternate timeframe is needed to respond, please contact me to make arrangements.

Your diagrams must be accompanied by a business-style transmittal letter containing the identifying elements for the license and this location, which must be currently dated and legibly signed by a senior management official.

Please only send one complete response by only one means of transmission to facilitate correct processing in our offices. Sending a fax to my attention at 630-515-1078 is the fastest and most reliable means of transmission. Do not, under any circumstances, also send us an emailed copy and/or a mailed copy; only one means of transmission and only one complete copy should be sent.

For future information, we must always have facility diagrams to accompany location of use additions to your license. The new location's address will appear in Condition No. 10, when approved, but the facility itself is connected to the license via diagrams linked to the new address in a document which is then placed in the last condition of the license called "the tie-down condition." This is how it becomes a part of your license.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate corrections and answers.

If you have any questions concerning this amendment please contact me at either (630) 829-9841 or (800) 522-3025, ext. 9841. My fax number is 630-515-1078. My email address is colleen.casey@nrc.gov.

You will be periodically inspected by NRC. Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you.

This could include issuance of a notice of violation, or imposition of a civil penalty, or an order suspending, modifying or revoking your license as specified in the General Statement of Policy and Procedure for NRC Enforcement Actions.

Since serious consequences to employees and the public can result from failure to comply with NRC requirements, prompt and vigorous enforcement action will be taken when dealing with licensees who do not achieve the necessary meticulous attention to detail and the high standard of compliance which NRC expects of its licensees.

NRC's Regulatory Issue Summary (RIS) 2005-31 provides criteria to identify security-related sensitive information and guidance for handling and marking of such documents. This ensures

J. Sutkowski

- 3 -

that potentially sensitive information is not made publicly available through ADAMS, the NRC's electronic document system.

Pursuant to NRC's RIS 2005-31 and in accordance with 10 CFR 2.390, the enclosed license document is exempt from public disclosure because its disclosure to unauthorized individuals could present a security vulnerability.

The RIS may be located on the NRC Web site at: <http://www.nrc.gov/reading-rm/doc-collections/gen-comm/reg-issues/2005/ri200531.pdf> and the link for frequently asked questions regarding protection of security related sensitive information may be located at: <http://www.nrc.gov/reading-rm/sensitive-info/faq.html>.

A copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system "Agencywide Documents Access and Management System" (ADAMS).


The NRC's document system is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

The NRC's Safety Culture Policy Statement became effective in June 2011. While a policy statement and not a regulation, it sets forth the agency's *expectations* for individuals and organizations to establish and maintain a positive safety culture.

You can access the policy statement and supporting material that may benefit your organization on NRC's safety culture Web site at <http://www.nrc.gov/about-nrc/regulatory/enforcement/safety-culture.html>.

We strongly encourage you to review this material and adapt it to your particular needs in order to develop and maintain a positive safety culture as you engage in NRC-regulated activities.

Sincerely,



Colleen Carol Casey
Materials Licensing Branch

License No. 13-00142-02
Docket No. 030-01580

Enclosure:

Amendment No. 109