



**Consumers
Power
Company**

D. Lankham
REGULATORY DOCKET FILE COPY

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

November 16, 1977



Mr James G Keppler
Office of Inspection and Enforcement
Region III
US Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

DOCKET 50-255 - LICENSE DPR-20 - PALISADES
PLANT - ER-77 - EXCESSIVE LEAKAGE FROM
CONTAINMENT PURGE VALVE

Attached is a reportable occurrence related to excessive leakage from a
Palisades Plant containment purge valve.

David P Hoffman
Assistant Nuclear Licensing Administrator

CC: ASchwencer, USNRC

NOV 21 1977

Palisades

[PLEASE PRINT ALL REQUIRED INFORMATION]

EVENT DESCRIPTIONCAUSE DESCRIPTION

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
--------------------	---------	--------------	------------------------	-----------------------

PERSONNEL EXPOSURES

PERSONNEL INJURIES

PROBABLE CONSEQUENCES

LOSS OR DAMAGE TO FACILITY

PUBLICITY

ADDITIONAL FACTORS

18 (Event Description Contd) - see ER-77-38. Inboard valve was torqued tightly closed
7 8 9 80

19 and tested satisfactorily.
7 8 9 80