

REGULATORY FILE COPY




**Consumers  
Power  
Company**

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

December 10, 1975

Director of Nuclear Reactor Regulation  
Att: Mr Robert A. Purple, Chief  
Operating Reactor Branch No 1  
US Nuclear Regulatory Commission  
Washington, DC 20555



DOCKET 50-255, LICENSE DPR-20  
PALISADES PLANT, CORRECTION TO AO-75-14

A review of AO-75-14, reported July 8, 1975, has disclosed an error in the information reported under Item 10, Failure Data. The second paragraph of Item 10 incorrectly indicated that all 2400 V bus breakers had been inspected prior to the occurrence reported as AO-75-14. This paragraph should read:

During the year previous to this occurrence (AO-75-14) all 2400 V breakers on bus 1D were cleaned and inspected under MO SPS-74-06. No deficiencies were noted during this inspection.

While this change is considered to be insignificant, we believe that it should be made to correct the record.

David A. Bixel  
Assistant Nuclear Licensing Administrator

CC: JGKeppler, USNRC  
File

13896