

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

Central file

50-255

July 30, 1975

A. IE Inspection Report No. _____

Transmittal Date : _____

Distribution:
IE Chief, FS&EB
IE:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
IE Files
IE Chief, M&PPB
L:D/D for Reactor Project

B. IE Inquiry Report No. _____

Transmittal Date : _____

Distribution:
IE Chief, FS&EB
IE:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ
DR Central Files
IE Files

C. Incident Notification From: Consumers Power Company 50-255
(Licensee & Docket No. (or License No.))

Transmittal Date : August 21, 1975 Palisades Plant

Distribution:
IE Chief, FS&EB
IE:HQ (4)
Licensing (4)
DR Central Files
IE Files

Distribution:
IE Chief, FS&EB
IE:HQ (4)
L:D/D for Fuels & Materials
DR Central Files
IE Files



*4041
3*

D() TB() LB() INFO()



Telegram

0 205

VEC101(1046)(1-010653C216)PD 08/04/75 1043

1975 AUG -4 AM 10:50

TLX CONSPower JKN

ZCZC 001 DLY JACKSON MICH 8/4/75

PMS USNRC

MR K R BAKER

NUCLEAR REGULATORY COMMISSION (FORMERLY AEC)

REGION III

799 ROOSEVELT ROAD

GLEN ELLYN, IL 60137

AC312 BOOK NO. OPR. NO.
TELEPHONE NBR. 858-2660
TELEPHONED TO J.D.K. BY 96.
DATE DLD. 08-04 TIME 11380
ATTEMPTS TO DELIVER:

60-255

AT APPROXIMATELY 0215 HOURS ON AUGUST 4, 1975 DIESEL GENERATOR 1-1 WAS BEING LOAD TESTED AND WAS OBSERVED TO HAVE EXCESSIVELY HIGH CYLINDER TEMPERATURES AND HIGH EXHAUST TEMPERATURES. DIESEL OPERATION WAS STOPPED AND THE UNIT DECLARED INOPERABLE. WHILE INVESTIGATION OF CAUSE OF PROBLEM WAS BEGUN. PRESENTLY INVESTIGA-

SF-1201 (R5-69)

TION IS CONTINUING.

J G LEWIS/G H HEIN
PALISADES PLANT
CONSUMERS POWER COMPANY
ALL CH

CC: R L HAUETER
R B SEWELL

NNNN

AUG 7 1975

SERVICED FOR
BETTER
DOWNERS. ADDRESS

7/24

1975 JUL 24 PM 1 42

50-255

CANCEL/Blenda
8/1

O
WU AGCY WHEA

WU MVN ILL
WUA113 GE 1102A CDT
ZCZC 002 DLY JACKSON MICHIGAN 7-24-75
USNRC
MR KEN BAKER atomic Energy Commission
NRC REGION III
799 ROOSEVELT ROAD
GLEN ELLYN IL 60137

SUBJECT A O 75-16 EXCEEDING RADWASTE BATCH DISCHARGE RATE
DURING THE RELEASE OF RADWASTE BATCH 75-021-R THE FLOW CONTROLLER
FIC 1050 MALFUNCTIONED. THE BATCH WAS RELEASED AT 102.2 GPM INSTEAD
OF THE 40 GPM SETPOINT. THIS RESULTED IN THE RELEASE GOING OUT AT
1.19 MPC.

CC R B SWEWLL

K W BERY
PALISADES PLANT
CONSUMERS POWER COMPANY
ALL CH

RPT K W BERRY

NNNN

AUG 11 1975

D() TB(89) 1240P9 WG WUN 7-30



Telegram

1975 JUL 30 AM 10: 17

VEB101(1013)(1-010543C211)PD 07/30/75 1011

TLX CONSPower JKN

0 246

ZCZC 001 DL JACKSON MICH 7-30-75

PMS NUCLEAR REGULATORY COMMISSION

REGION III

799 ROOSEVELT ROAD

GLEN ELLYN ILL 60137

AC 312 BOOK NO 3-2 OPR. NO.

TELEPHONE NO. 858-2660

TELETYPE NO. 1628 BY man

DATE 7/30 TIME 1447

ATTEMPT TO 7-30 1445A

SUBJECT- WASTE GAS DECAY TANK T 101 C

WASTE GAS DECAY TANK T 101 C HAS LOST 11 LB PRESSURE, OTHER THAN SAMPLING, SINCE BEING ISOLATED. THE TANK LOST 4 LB ON 7-18-75

BETWEEN 1700 AND 2300, 5 LB ON 7-28-75 BETWEEN 0030 AND 0900 AND

2 LB BETWEEN THE TWO PERIODS. WE ARE REPORTING THIS AS A VIOLATION

OF THE 15 DAY HOLD-UP PERIOD. NO ACTIVITY LIMITS WERE VIOLATED.

J G LEWIS

PALISADES PLANT SUPT

CONSUMERS POWER COMPANY

JACKSON MICHIGAN

ALL JC

NN

NN

NNNN

AUG 1 1975