



**Second Interim Notification per 10 CFR Part 21  
January 11, 2019**

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001  
Fax: (301) 816-5151

This letter is a follow-up to the initial Interim Notification dated October 12, 2018 (Ref. ML18302A229).

ABB continues to work with Flowserve-Limitorque to expedite the additional inspections of motors in the field and testing of motors pulled from inventory. The testing is necessary to assist in determination if the abnormal appearance and deformation constitutes a defect which would cause a substantial safety hazard.

It is anticipated that this will be completed by February 28, 2019. At that time, motor testing should be complete and analysis of results conducted. ABB will then be able to determine if the nature of the condition is a substantial safety hazard and reportable. If further time is necessary for evaluation, a follow-up to this report will be filed.

Since discovery of the condition, and to date of this report, ABB and Flowserve-Limitorque are not aware of any confirmed field inspections by Flowserve-Limitorque's customer or the results of such inspections.

Sincerely,

A handwritten signature in black ink, appearing to read 'Sheldon Thomas', is written over a horizontal line.

Sheldon Thomas  
QA Manager, ABB Motors and Mechanical Inc.  
Flowery Branch, GA 30542

cc:  
Jeff McConkey, Flowserve-Limitorque QA Manager

ABB MOTORS AND MECHANICAL INC.  
4349 AVERY DRIVE  
FLOWERY BRANCH, GA 30542  
+1 678 947 7350