

### LICENSEE EVENT REPORT

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 57 CAT 58

0	1	C	0	F	S	V	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	2	0	4			5
		LICENSEE CODE						LICENSE NUMBER										LICENSE TYPE					CAT					

CON'T

0 1 7 8

REPORT SOURCE

L 6 60 61 U 5 0 0 0 2 6 7 68 7 69 0 8 1 7 7 9 74 8 75 0 8 3 1 7 9 80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On August 17, 1979, while operating at approximately 50% of rated power it was determined that a recent pipe hanger installation on the PCRV cooling water lines would have prevented proper installation of pipe spools to the high temperature filter adsorber coolers. These are required to be installed and operable within 1 1/2 hours of an extended loss of forced circulation. This does not meet the requirements of Fort St. Vrain Technical Specifications LOO 4.2.18 and is reportable per AC 7.5.2(a)5.

SYSTEM CODE C B (11)		CAUSE CODE B (12)		CAUSE SUBCODE C (13)		COMPONENT CODE S U P P O R T (14)				COMP. SUBCODE A (15)		VALVE SUBCODE Z (16)	
LER/RO REPORT NUMBER 7 8		EVENT YEAR 7 9 (17)		SEQUENTIAL REPORT NO. 0 2 7 (18)		OCCURRENCE CODE 0 1 (19)				REPORT TYPE T (20)		REVISION NO. 0 (21)	
ACTION TAKEN B (18)		FUTURE ACTION A (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22)		ATTACHMENT SUBMITTED Y (23)		NPRD-4 FORM SUB. N (24)	
PRIME COMP. SUPPLIER N (25)		COMPONENT MANUFACTURER G 0 6 3 (26)											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Hanger additions to the system piping caused the pipe ends to change alignment and

1 1 made the spool pieces inoperable. The spool pieces were modified to fit on the

1 2 available purification train and will be modified on the other train after it is re-

1 3 moved from service. There was no affect on public safety or health.

1 4

8 9 FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 E 0 3 0 N/A C In House Audit

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) N/A

7 8 9 10 11 44 45 90

PERSONNEL EXPOSURES				DESCRIPTION (39)	
NUMBER			TYPE		
1	7	000	(37) Z	(38)	N/A

PERSONNEL INJURIES										
NUMBER			DESCRIPTION							
1	2		0	0	0	(40)	N/A			

930320

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
1 9 2 Z (42) N/A 7909100575

PUBLICITY  
 ISSUED (2) (0) (N) (44) DESCRIPTION (45) N/A  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20  
 NRC USE ONLY

NAME OF PREPARER

J. W. Gahm

PHONE: (303) 785-2253