

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
716 Edney Building

September 12, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

POOR ORIGINAL

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BPRO-50-259/7913

The enclosed report is a supplement to my letter dated August 6, 1979,
concerning TVA's field inspection and evaluation program of self-drilling
expansion anchors which is continuing in accordance with IE Bulletin 79-02
with unit 1 at 1,035 MWe, unit 2 at 1,095 MWe, and unit 3 in outage.
This report is submitted in accordance with Browns Ferry unit 1 Technical
Specification 6.7.2.a(9).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

356313

A002
5/1