

50-413

DUKE POWER COMPANY
ELECTRIC CENTER, BOX 33189, CHARLOTTE, N. C. 28242

L. C. DAIL
VICE PRESIDENT,
DESIGN ENGINEERING

707 227 A10:10

August 21, 1979


Mr. J. P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Catawba Nuclear Station
Steam Generator Water Level
Measurement System Errors
50.55(e) Report: IE-79/02-5DD-413/414
Duke File: CN-1412.11.1

Dear Mr. O'Reilly:

The referenced 10CFR 50.55(e) reportable item was reported by letter dated June 22, 1979, from Mr. T. M. Anderson, Manager, Nuclear Safety Westinghouse to Mr. Victor Stello, Director, Office of Inspection and Enforcement, U. S. Nuclear Regulatory Commission. Attached is Duke's Power's interim report concerning this item. Duke will submit a final report upon resolution of this generic deficiency.

Very truly yours,



L. C. Dail, Vice-President
Design Engineering

EKM/cam

Attachments

cc: W. H. Owen	W. O. Henry	L. E. Suther
C. J. Wylie	T. C. McMeekin	R. O. Sharpe
J. R. Wells	D. G. Owen	R. P. Harrall

B019
5/11

956351

7909170 471

790116
OFFICIAL COPY