

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	G	A	E	I	H	2	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5			
2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30			
		LICENSEE CODE								LICENSE NUMBER													LICENSE TYPE						CAT		

CON'T

REPORT SOURCE 1 6 0 5 0 0 0 3 6 6 7 0 8 2 7 7 7 8 0 9 1 2 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

07 | The cooling water to RHR service water pumps 2B and 2D was found to be less

03 | than the amount needed to cool the bearings properly. There was no affect on

04 | the environs. There have been no similar occurrences of this type.

05 | 1

0	6
---	---

0	7	
---	---	--

08 |

7 6 5

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 S H 11 E 12 E 13 I N S T R U 14 C 15 Z 16

2 8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER RO REPORT NUMBER EVENT YEAR
79--
 21 22 23

SEQUENTIAL REPORT NO. 097/
 24 25 26 27

OCCURRENCE CODE 03
 28 29

REPORT TYPE L-
 30 31

REVISION NO. 0
 32

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
E	18	Z	19	Z	20	Z	21	0	0	0	0	N	23	N	24	A	25	F	1	3	0
33		34		35		36		37			40	41		42		43		44			45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The pressure controller for valve 2E11-F126B, cooling water flow control valve,

11 | was not controlling the valve position properly. The controller was tuned

[1] [2] | to allow the proper cooling water flow. 2E11-F126A was checked and found

13 | to be operating properly.

1	4
---	---

7	8	9											8	
FACILITY STATUS			% POWER			OTHER STATUS (30)			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION (32)		
1	5	E (28)	0	6	9 (29)	NA			A (31)	Operator observation				

ACTIVITY CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
RELEASED	OF RELEASE				
1	6	Z	33	Z	34
		NA		NA	

PERSONNEL EXPOSURES.									
NUMBER		TYPE		DESCRIPTION					
1	7	0	0	0	17	Z	38	NA	

PERSONNEL INJURIES		DESCRIPTION		NA		POOR	
NUMBER							
1	0	0	0	30			

LOTS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION

(1) (9) (2) (47)

NA

ORIGINAL

7909190461

PUBLICITY
 ISSUED DESCRIPTION (45)
 NA
 977.115
 NRC USE ONLY
 68 69

NAME OF PREPARED R. T. Nix

PHONE 912-367-7781

NRC USE ONLY