

Georgia Power Company
230 Peachtree Street
Post Office Box 4545
Atlanta, Georgia 30302
Telephone 404 522-6060

USNRC REGION II
ATLANTA, GEORGIA

TIC



Georgia Power

the southern electric system

Power Generation Department

13 SEP 17 AIO: 33

September 14, 1979

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

REFERENCE:
RII: JPO
50-321/50-366
IE Bulletin 79-02

ATTENTION: Mr. James P. O'Reilly

Gentlemen:

In Georgia Power Company's response of July 6, 1979, IE Bulletin 79-02, a complete description and the results of the Plant Hatch Unit 1 anchor bolt replacement program were deferred until completion of the replacement process. Additionally, NRC inspector Mr. E. J. Vallish, at an August 15, 1979, inspection, recommended that the Unit 1 response of July 6 be supplemented to address each point of IE Bulletin 79-02 in a manner similar to the Unit 2 portion of that response.

Georgia Power Company hereby submits a supplemental response to IE Bulletin 79-02 to address these two points. Should you have any questions, please contact my office.

Yours very truly,

L. T. Widner

W. A. Widner
Manager of Nuclear Operations

WEB/mb

xc: Director of the Office of Inspection and Enforcement
Director of the Division of Operating Reactors,
Office of Nuclear Reactor Regulation

Enclosure

1037 129

790400
ORIGINAL COPY

7909280631