

TERA

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

August 8, 1979

13 AUG 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. 530A
PO/FHT:scj
Docket No. 50-339
License No. CPFR-78

Subject: IE Bulletin 79-13 Amended Response

Dear Mr. O'Reilly:

Our July 13, 1979, letter, Serial no. 530, in response to IE Bulletin 79-13, "Cracking in Feedwater System Piping", stated that the North Anna Unit 2 feedwater piping had been inspected on June 27, 1979. This is incorrect, as only the steam generator inlet nozzles have been inspected to date. The remaining inspection effort will be completed in a timely manner consistent with the requirements of the subject bulletin.

Very truly yours,

C. M. Stallings

C. M. Stallings
Vice President-Power Supply
and Production Operations

POOR
ORIGINAL

1056 080

7909290364

790300

Q OFFICIAL COPY