



MISSISSIPPI POWER & LIGHT COMPANY  
Helping Build Mississippi  
P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

PRODUCTION DEPARTMENT

*Contable*  
*50 416*  
*417*

Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region II - Suite 818  
230 Peachtree Street, N. W.  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Director

Gentlemen:

SUBJECT: Grand Gulf Nuclear Station  
File 0272/L-850.0/L-452.0  
Evaluation of IEB - 78-05  
\*MAEC78/21\*  
REF: RII:JPO 50/416, 50/417  
AECM-78/40

We have completed our review of IE Bulletin 78-05 entitled "Malfunctioning of Circuit Breaker Auxiliary Contact Mechanism - General Electric Model CR 105X". This mechanism is not utilized on any equipment at the Grand Gulf Nuclear Station. Based on this finding, we are planning no further action in response to this bulletin.

Yours truly,

*for* J. P. McGaughy, Jr.  
Director of Power Production

JRF/WDH/LFD:db

cc: Mr. R. C. Travis  
Mr. T. B. Conner

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Construction Inspection  
Washington, D. C. 20555

7910010 842 *as* *db*

Member Middle South Utilities System

1033 273