



Public Service Company of Colorado

16805 Weld County Road 19 1/2, Platteville, Colorado 80651

September 28, 1979
Fort St. Vrain
Unit No. 1
P-79223

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

REF: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/79-34/03-L-0, Preliminary, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/79-34/03-L-0.

Very truly yours,

Don Warembourg
Don Warembourg
Manager, Nuclear Production

DW/alk

cc: Director, MIPC

D002
5/11

1083 350

7910030

497

S