

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	14						15	25										26	30					57	CAT	58			
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE										

REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 9 0 8 7 9 8 1 0 0 1 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a normal reactor startup, the operator noticed that rod 26-07 had no position

03 | indication at notch 48. All other indications were normal.

04 | Technical Specification 3.1.3.7, 6.9.1.9b

05 _____

06 _____

0	7	
---	---	--

0	8	
---	---	--

SYSTEM CODE I D 11		CAUSE CODE E 12		CAUSE SUBCODE A 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE I 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 7 8		EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 7 6 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32	
ACTION TAKEN X 18		FUTURE ACTION X 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23	
NPRD-4 FORM SUJ. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER G 0 8 0 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	Rod 26-07 was operationally tested and no problem could be found with position indica-
---	---	--

1 | ting probe. The rod was notch in to notch 46 and back to notch 48 and normal indica-

tion returned. An Engineering Work Request had been written to investigate the

13 | position indicating system due to the number of position indicating failure we have

1 4 | been experiencing.

FACILITY STATUS (1) 5 (C) (28) % POWER (0) 3 (0) (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (A) (31) Operator Surveillance DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

		PERSONNEL INJURIES						
		NUMBER			DESCRIPTION			(41)
1	8	0	0	0	(40)	NA		

		LOSS OF OR DAMAGE TO FACILITY		(43)
		TYPE	DESCRIPTION	
1	9	Z(42)	NA	1114 127

8 9 10 80

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) NA 7910090397

NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521