

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

L	6	0	5	0	0	3	1	8	7	0	9	0	5	7	9	8	1	0	0	4	7	9	6
60	61								68	69					74		75						80
DOCKET NUMBER										EVENT DATE						REPORT DATE							

02 At 1755 the operator observed Channel D Nuclear Instrumentation System (RPS)

03 linear power range indicating erratically high. High power, thermal margin

04 power/low pressure, and axial shape index trip units were placed in bypass per

05 T.S.3.3.1.1. Linear power was returned to service at 1335 9/6/79. The three

06 redundant channels remained operable during the event. This has not been a

07 repetitive event.

08		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP SUBCODE		VALVE SUBCODE		LER-RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																																																																					
I A		X		Z		I N S T R U		X		Z		7 9		0 3 2		0 3		L		0		X		Z		Z		Z		0 0 0		N		Y		N		C 4 9 0																																																																							

1 0 While troubleshooting, technicians observed 1-NI-008 signal level change when  
1 1 the power was moved. After clearing drawers rails, signal level returned to  
1 2 normal and remained steady. Apparent cause - inadequate chassis ground. The  
1 3 remaining three channel drawers will be cleaned during the next refueling  
1 4 outage to commence October, 1979.

FACILITY STATUS (28) E  
 % POWER (29) 1 0 0  
 OTHER STATUS (30) NA  
 METHOD OF DISCOVERY (31) A  
 DISCOVERY DESCRIPTION (32) Operator Observation  
 ACTIVITY CONTENT RELEASED OF RELEASE (33) Z  
 AMOUNT OF ACTIVITY (34) NA  
 PERSONNEL EXPOSURES NUMBER (35) 0 0 0  
 TYPE (36) Z  
 DESCRIPTION (37) NA  
 PERSONNEL INJURIES NUMBER (38) 0 0 0  
 DESCRIPTION (39) NA  
 LOSS OF OR DAMAGE TO FACILITY TYPE (40) Z  
 DESCRIPTION (41) NA  
 PUBLICITY ISSUED (42) N  
 DESCRIPTION (43) NA  
 NRC USE ONLY (44) 1130 027  
 7910110391  
 POOR ORIGINAL

NAME OF PREPARED S. M. Davis/P. G. Rizzo

PHONE (301) 234-7942/7386

**POOR ORIGINAL**