

**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	1	4	5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER												25	26	LICENSE TYPE						30	57	CAT	58

CON'T

7 8      60 61      DOCKET NUMBER      68 69      EVENT DATE      74 75      REPORT DATE      80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1740 the operator started receiving high power and thermal power/low pressure

0 3 | (TM/LP) pre-trips and trip alarms on reactor protection system (RPS), Channel C.

0 4 | Channel C high power and TM/LP trip units were bypassed per T.S.3.3.1.1. for

0 5 | troubleshooting. The trip units were returned to service at 0940 on 9/8/79.

0 6 | The three redundant channels remained operable during the event. This has not

0 7 | been determined to be a repetitive event.

08		9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
0	8			I	A	X		Z		I	N	S	T	R	U	X		Z	
7	8	9		11	10	11	12	12	13	13	14	15	16	19	20				
09		10		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
0	9			7	9		0	3	3		0	3		0					
7	8	9		21	22	23	24	25	26	27	28	29	30	31					
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
Z	X			Z		Z		0	0	0	N	N		N		W	1	2	0
17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Symptoms above are sporadic. Linear power range detector 1-NE-007 subchannel

1 1 signals were found to be noisy. Suspect dirty or moist detector cables. Maintenance Request No. 0-79-408 records problem for further work during the refueling

1 2 outage commencing October, 1979.

1 3

7 8 9 80

1 5 FACILITY STATUS E 28 1000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 2 33 3 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	0
		(37)	Z	(38) NA

PERSONNEL INJURIES		DESCRIPTION		NA	
NUMBER					
1	8	0	0	0	40

1130 098

7	8	9	11	12	80
LOSS OF OR DAMAGE TO FACILITY (43)					
TYPE		DESCRIPTION			
1	9	Z (42)	NA	7 9 1 0 1 1 0 41.5	

7	8	9	10											80		
			PUBLICITY	(45)											NRC USE ONLY	
			ISSUED	DESCRIPTION												
2	0		NI	(44)	NA											

NAME OF PREPARER S. M. Davis/P. G. Rizzo PHONE: (301) 234-7942/7986