

**LICENSEE EVENT REPORT**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

|   |   |
|---|---|
| 0 | 1 |
|---|---|

REPORT SOURCE

|    |     |               |   |   |   |   |   |    |    |            |   |   |   |   |   |    |     |             |   |   |   |   |   |     |
|----|-----|---------------|---|---|---|---|---|----|----|------------|---|---|---|---|---|----|-----|-------------|---|---|---|---|---|-----|
| L  | (6) | 0             | 5 | 0 | - | 0 | 3 | 2  | 4  | (7)        | 0 | 9 | 1 | 8 | 7 | 9  | (8) | 1           | 0 | 0 | 9 | 7 | 9 | (9) |
| 60 | 61  | DOCKET NUMBER |   |   |   |   |   | 68 | 69 | EVENT DATE |   |   |   |   |   | 74 | 75  | REPORT DATE |   |   |   |   |   | 80  |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

|  |    |                    |    |                                |    |                               |    |                  |    |                           |    |                       |    |                           |    |
|--|----|--------------------|----|--------------------------------|----|-------------------------------|----|------------------|----|---------------------------|----|-----------------------|----|---------------------------|----|
| SYSTEM CODE<br>0 9                       |    | CAUSE CODE<br>S B  |    | CAUSE SUBCODE<br>E             |    | COMPONENT CODE<br>I N S T R U |    |                  |    |                           |    | COMP. SUBCODE<br>R    |    | VALVE SUBCODE<br>Z        |    |
| 7  | 8  | 9                  | 10 | 11                             | 12 | 13                            | 14 | 15               | 16 | 17                        | 18 | 19                    | 20 | 21                        | 22 |
| LER/RO REPORT NUMBER<br>17               |    | EVENT YEAR<br>7 9  |    | SEQUENTIAL REPORT NO.<br>0 8 5 |    | OCCURRENCE CODE<br>0 3        |    | REPORT TYPE<br>L |    | REVISION NO.<br>0         |    |                       |    |                           |    |
| ACTION TAKEN<br>B                        |    | FUTURE ACTION<br>X |    | EFFECT ON PLANT<br>Z           |    | SHUTDOWN METHOD<br>Z          |    | HOURS<br>0 0 0 0 |    | ATTACHMENT SUBMITTED<br>N |    | NPRD-4 FORM SUB.<br>Y |    | PRIME COMP. SUPPLIER<br>A |    |
| 33                                       | 34 | 35                 | 36 | 37                             | 38 | 39                            | 40 | 41               | 42 | 43                        | 44 | 45                    | 46 | 47                        |    |
| CAUSE DESCRIPTION AND CORRECTIVE ACTIONS |    |                    |    |                                |    |                               |    |                  |    |                           |    |                       |    |                           |    |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

8 9  
FACILITY STATUS (28) 1 5 E  
% POWER 0 8 2 (29) NA OTHER STATUS (30)  
METHOD OF DISCOVERY (31) A Operator Surveillance DISCOVERY DESCRIPTION (32)

| PERSONNEL EXPOSURES |   |   |      |             |      |   |      |    |      |
|---------------------|---|---|------|-------------|------|---|------|----|------|
| NUMBER              |   |   | TYPE | DESCRIPTION |      |   |      |    |      |
| 1                   | 7 | 0 | 0    | 0           | (37) | Z | (38) | NA | (39) |

| 1 9  |  | Z           |  | 42 |  | NA |  |
|------|--|-------------|--|----|--|----|--|
| TYPE |  | DESCRIPTION |  |    |  |    |  |
|      |  |             |  |    |  |    |  |

PUBLICITY  
ISSUED DESCRIPTION (45)  
7 9 1 0 1 7 0 2 1 6  
N (44) NA  
NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521