

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

λ CUNT

0	1
---	---

 λ μ

REPORT
SOURCE

L	6	0	5	0	0	0	3	6	6	7	1	0	1	7	7	9	8	1	0	3	0	7	9	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	During normal power operation Unit One made the shared D/G 1B inoperative for main-
---	---	---

03 | tenance and failed to notify Unit Two personnel in time for Unit Two to comply with

0	4
---	---

 | their Technical Specifications Section 4.8.1.1.1.a and 4.8.1.1.2.a.4 within one hour.

05 This is a non repetitive occurrence.

06 _____

0	7	
---	---	--

08 _____

7 8 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 0 9 11 12 13 14 15 16
 2 8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER RO REPORT NUMBER 7 9 — 1 0 9 / 0 3 L — 0

ACTION TAKEN H 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The cause has been attributed to personnel error for not notifying Unit Two of out-
---	---	---

11 | age on 1B Diesel Generator. Unit Two personnel were notified 2 1/4 hours after 1B D/G

1 2 was made inoperative and the requirements of Technical Specifications Section

4.8.1.1.1.a and 4.8.1.1.2.a.4 were completed 3½ hours after the 1B D/G had been

1 4 | made inoperative. Standing Order #79-55 has been issued requiring (continued)

7 8 9
FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)
1 5 E 0 9 8 NA Z NA

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 3 4 5 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NA NA

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	2	0	0	0
		37	Z	38
				NA

7		8		9		11		12		13	
						PERSONNEL INJURIES					
						NUMBER		DESCRIPTION			
1	R	0	0	0	40			NA		1329 311	

8		9		11		12	
LOSS OF OR DAMAGE TO FACILITY				(43)			
TYPE		DESCRIPTION					
1	9	Z	(42)	NA			
				7911140 28.5			

7 8 9 10

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) NA

NRC USE ONLY

NAME OF PREPARER S. X. Baxley, Supt. of Operations

PHONE: 912-367-7781

917-920

Caused Description (Continued)

the shift supervisor to be notified prior to shared equipment outages so he can insure the other unit is aware of outage. This standing order will be incorporated in a plant procedure prior to February 1, 1980.

1729 312