

74-006-03L
79-004-03L
79-005-03L
79-004-03L

79-004-03L
79-003-03L

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

October 26, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCY -
TENSILE ANCHOR CAPACITIES LOWER THAN ASSUMED IN DESIGN ALLOWABLES
(NCR CEB-79-16 AND NCR CEB 79-17)

Initial report of the subject deficiency was made to Mike Gouge, NRC-OIE, Region II on May 7, 1979. The first and second interim reports were submitted on May 24, 1979, and August 13, 1979, respectively. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the final report of the subject deficiency. If you have any questions concerning this matter, please call Tish Jenkins at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L M Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

1373 354

7911200

541
790222