

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 PABVS1 00-000000-000 341111 45
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE J0 57 CAT 58

01 REPORT SOURCE L 05000334 7030179 3111579 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a routine audit of Chemistry records on 10/22/79, it was observed that
03 samples of diesel fuel from the fuel storage tank for the emergency diesel
04 generators were being taken as required by the Technical Specifications. However,
05 during the period March through September, 1979, there were several occasions when
06 analysis of the samples was not completed within the required time. The samples
07 were immediately analyzed and found to be within acceptable limits for viscosity,
08 water and sediment.

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
EE 11 DD 12 ZZ 13 ZZZZZZ 14 Z 15 Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LER/RC REPORT NUMBER EVENT YEAR 79 21 22 SEQUENTIAL REPORT NO. 043 23 24 OCCURRENCE CODE 03 25 26 REPORT TYPE L 27 28 REVISION NO. 0 29 30
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
HG 18 19 Z 20 Z 21 0000 22 N 23 N 24 Z 25 Z999 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Chemistry personnel failed to analyze the samples within the allowable time limits
11 because of incomplete instructions in the Chemistry manual for Modes 5 and 6. The
12 Chemistry manual was revised to clarify Technical Specification sampling and
13 analysis requirements. Chemistry personnel were issued letters stressing the
14 importance of timely analysis of samples.

15 FACILITY STATUS Z 28 % POWER 000 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION Records review 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
16 RELEASED OF RELEASE Z 33 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 000 37 Z 38 N/A 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
18 PERSONNEL INJURIES NUMBER DESCRIPTION 000 40 N/A 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION Z 42 N/A 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
20 PUBLICITY ISSUED DESCRIPTION N 44 N/A 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER J. A. Werling

PHONE 412-643-1258

NRC USE ONLY