

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

November 16, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT ALL UNITS - REPORTABLE DEFICIENCY - GRIT
BLASTING OF FABRICATED PIPING ASSEMBLIES (NCR HNP-A-068)

Initial report of the subject deficiency was made to R. W. Wright, NRC-OIE, Region II on October 19, 1979. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the first interim report of the subject deficiency. It is anticipated that the final report will be transmitted to you on or before January 31, 1980. If you have any questions concerning this matter, please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1391 023

Bol
5/1