

RADIATION SAFETY SERVICE
THE UNIVERSITY OF KANSAS
Lawrence, Kansas 66045

CENTRAL FILES

PDR:HQ

TIC

NSIC

Nuclear Reactor Center

October 23, 1979

Karl V. Seyfrit
Director
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012


Dear Mr. Seyfrit:

In response to the IE Bulletin No. 79-19 and Docket No. 50-148, we wish to indicate that we do not generate wastes of the type which require disposal by burial. Our disposal is either by decay (short-lived isotopes) or by sanitary sewer at levels which are much below the values specified in 10 CFR 20.303.

Thus the answer is "no" for questions 1-3 with the understanding that this means that none of our wastes are disposed of via burial.

On this basis, no further action need be taken.

Sincerely yours,



Russ Mesler
Reactor Supervisor



Benjamin S. Friesen
Radiation Safety Officer

1396 316

7911270 001

Q