



Metropolitan Edison Company
Post Office Box 480
Middletown, Pennsylvania 17057
717 944-4041

Writer's Direct Dial Number

November 27, 1979
GQL 1452

Director of Nuclear Reactor Regulation
Attn: R. W. Reid, Chief
Operation Reactor Branch No. 4
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555


Dear Sir:

Three Mile Island Nuclear Station, Unit 1 (TMI-1)
License No. DPR-50
Docket No. 50-289
IGSCC Investigation

In response to your letter of October 30, 1979, concerning the subject issue, the information requested in Part A was sent to your office on October 19, 1979 (letter GQL 1450). The information contained in this letter responds to each request as follows:

- 1) The information requested in Item 1 was provided in Attachments 3, 4, and 5.
- 2) The information requested in Item 2 was provided in Attachment 3.
- 3) The information requested in Item 3 was provided in Attachment 2, with the exception of identifying the welds that will be repaired prior to restart and the welds with indications to be left in place in the piping and monitored to determine potential flaw growth rate. This information is currently being generated and will be submitted prior to TMI-1's restart.

Sincerely,


J. C. Herbein
Vice President-Nuclear Operations

JGH:DWR:tas

1439 354

ADD 5/10
ADD: 4 SILVER 10