

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	O	F	S	V	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	2	0	4		5							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35							
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE										57 CAT 58	

CON'T

0	1	L	6	0	5	0	0	0	2	6	7	7	1	0	3	0	7	9	8	1	1	2	9	7	9	9					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35			
REPORT SOURCE		DOCKET NUMBER										EVENT DATE										REPORT DATE									

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On October 30, 1979, during normal surveillance testing, one of three reactor pressure

0 3 | transmitters was found to be out of calibration. This resulted in operation with

0 4 | instrument settings less conservative than required by Fort St. Vrain Technical

0 5 | Specification LCO 4.4.1, and is reportable per AC 7.5.2(b)1 and AC 7.5.2(b)2. There

0 6 | was no affect on public health or safety. Redundant system was available and operable,

0 7 |

0 8 |

0	9	C	J	11	E	12	E	13	I	N	S	T	R	U	14	T	15	Z	16	17	7	9	—	0	5	7	—	0	3	L	—	0	18	Z	19	Z	20	Z	21	0	0	0	0	Y	23	N	24	N	25	G	0	6	3	26
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50											
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE										COMP. SUBCODE		VALVE SUBCODE		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This problem was due to instrument drift. The instrument was recalibrated, and the

1 1 | test was successfully completed. No further action is anticipated.

1 2 |

1 3 |

1 4 |

1	5	G	28	0	0	0	29	N/A	30	B	31	Normal Scheduled Surveillance	32	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION						

1	6	Z	33	Z	34	N/A	35	N/A	36	
7	8	9	10	11	12	13	14	15	16	17
ACTIVITY CONTENT RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						

1	7	0	0	0	37	Z	38	N/A	39	
7	8	9	10	11	12	13	14	15	16	17
PERSONNEL EXPOSURES		TYPE		DESCRIPTION						

1	8	0	0	0	40	N/A	41			
7	8	9	10	11	12	13	14	15	16	17
PERSONNEL INJURIES		TYPE		DESCRIPTION						

1	9	Z	42	N/A	43					
7	8	9	10	11	12	13	14	15	16	17
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION						

2	0	N	44	N/A	45					
7	8	9	10	11	12	13	14	15	16	17
PUBICITY ISSUED		DESCRIPTION		NRC USE ONLY						

NAME OF PREPARER *W. J. [Signature]*

PHONE: (303) 785-2253