

DUKE POWER COMPANY
POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

November 9, 1979

TELEPHONE AREA 704
373-4083

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

MATERIAL TRANSMITTED HERewith
CONTAINS 2.790 MATERIAL

Re: RII:DEM
50-269/79-24
50-269/79-22
50-287/79-24

Dear Mr. O'Reilly:

With regard to your letter of September 27, 1979 which transmitted subject inspection report, please find attached responses to the cited items of non-compliance. At the exit interview following the inspection, it was the understanding of station personnel that all corrective action had been completed and no further response was required. A recent discussion with your staff revealed that a misunderstanding regarding responding to the report existed. Consequently, the attached responses are provided to address the corrective actions immediately taken as well as those measures taken to prevent recurrence.

Pursuant to 10CFR 2.790(d), this response, which involves security measures, should be withheld from public disclosure.

Very truly yours

William O. Parker, Jr.

William O. Parker, Jr. *by PAB*

RLG:scs
Attachment

1637 313

7912210

790647
OFFICIAL
248