



**Commonwealth Edison**

One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

TIC

December 28, 1979

Mr. James G. Keppler, Director  
Directorate of Inspection and  
Enforcement - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: Byron Station Units 1 and 2  
Braidwood Station Units 1 and 2  
Supplemental Response to IE Bulletin  
79-09, "Failures of GE Type AK-2 Circuit  
Breaker in Safety-Related Systems"  
NRC Docket Nos. 50-454/455 and 50-456/457

Reference (a): C. Reed letter to J. G. Keppler  
dated June 18, 1979

Dear Mr. Keppler:

In response to the subject bulletin, Commonwealth Edison committed to the development of a preventive maintenance program Type AK-2 circuit breakers (See Reference (a) for Byron and Braidwood Stations).

At the time those commitments were made it was assumed that sufficient information relative to these breakers would be available to allow for the maintenance program development; i.e. GE Circuit Breaker Instruction Manuals. Although we now have the required information, we will be unable to complete the development and approval of the program by the date committed.

This program as indicated in IE Bulletin 79-09, is intended to assure the performance of the subject breakers during plant operation. Therefore, we remain committed to the implementation of the maintenance program before fuel loading on the subject units. We expect to have completed the development and approval of the program in the first quarter of 1980. This change has been reviewed with Mr. E. Schwienbinz of your staff.

If you have any questions in this regard, please direct them to this office.

Very truly yours,

*D. Louis Peoples*

D. Louis Peoples  
Director of Nuclear Licensing

1755 342

JAN 3 1980

8001160

388