

Vepco

VIRGINIA ELECTRIC AND POWER COMPANY, RICHMOND, VIRGINIA 23261

May 24, 1979

DEMA

TERA

Mr. James P. O'Reilly, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Serial No. 413
PSE&C/DPB:adw:mc

Docket Nos. 50-404
50-405

Dear Mr. O'Reilly:

IE Bulletin 79-04 requested information concerning incorrect weights for swing check valves manufactured by Velan Engineering Corporation. No Velan check valves have been purchased for use on these units.

Very truly yours,

L. M. Stallings
for

Sam C. Brown, Jr.
Senior Vice President
Power Station Engineering
and Construction

cc: Mr. John G. Davis, Acting Director
Office of Inspection & Enforcement

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation

19 MAY 24 9:14

USNRC REGION II
ATLANTA GEORGIA

7907100183

316 323

790040
OFFICIAL COPY