

CONTROL BLOCK: [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	2	1	7	0	6	2	4	7	9	3	0	7	1	1	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | With the reactor shutdown for refueling, while performing procedure HNP-1-3801 (Diesel
0 3 | Generator Manual Start), the 1R43-S001 B Diesel Generator tripped after being tied to
0 4 | the bus and loaded for approximately 15 minutes. The requirements of Technical
0 5 | Specifications 3.9.B.2 and 3.9.C were complied with. Neither public health and safe-
0 6 | ty nor safe plant operation were affected by this incident.
0 7 |
0 8 |

0 9		SYSTEM CODE E E		CAUSE CODE E		CAUSE SUBCODE X		COMPONENT CODE E N G I N E				COMP. SUBCODE Z		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
17 LER RO REPORT NUMBER		EVENT YEAR 7 9		—		SEQUENTIAL REPORT NO. 0 4 1		—		OCCURRENCE CODE 0 3		REPORT TYPE L		—	
23		24		25		26		27		28		29		30	
ACTION TAKEN X		FUTURE ACTION X		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACH MENT SUBMITTED N		NPRO-4 FORM 508 Y		PRIME COMP SUPPLIER A	
33		34		35		36		37		40		41		42	
38		39		40		41		42		43		44		47	
48		49		50		51		52		53		54		55	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause that initiated the trip has not yet been determined. After the diesel gen-
1 1 erator relaying was checked to verify that a lockout had not been received, procedure
1 2 HNP-1-3801 was performed again and found satisfactory on 6-24-79. An investigation
1 3 is in progress to determine the cause for the trip and an update report will be sub-
1 4 mitted when the cause is determined.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	B	29	0	0	0	29	N/A	30	B	31	Surveillance Test	32	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 33 Z 34

AMOUNT OF ACTIVITY

N/A

LOCATION OF RELEASE

N/A

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	Z	N/A

PERSONNEL INJURIES		80
NUMBER	DESCRIPTION	
10107	N/A	

LOSS OF OR TYPE ☒ (42) ☐ (43) PAGE TO FACILITY OPTION ☒ (43) N/A 356 340

10
PUBLICITY
ISSUED DESCRIPTION (15)
N/A 7907170 060
NRC USE ONLY

NAME OF PREPARER R. T. Nix, Supt. of Maint.

PHONE 912-367-7781