

USNRC REGION II
ATLANTA, GEORGIA



Georgia Power

Power Supply Engineering and Services

June 13, 1979
JUN 13 1:32

United States Nuclear Regulatory Commission
Division of Reactor Operations Inspection
Office of Inspection and Enforcement
Washington, D. C. 20555

REFERENCE:
RII: JPO
50-321
50-366

ATTENTION: Director

Gentlemen:

The Georgia Power Company offers the following information in response to Mr. J. P. O'Reilly's letters of February 8, 1979, and June 6, 1979, requesting information concerning IE Bulletins 79-01 and 79-01A.

An engineering review of the environmental qualification of Class 1E equipment on Hatch Units 1 and 2 is being performed for compliance with IE Bulletin 79-01. The review is presently incomplete; however, certain items have been identified as not meeting full environmental qualifications. The items are the Reactor Water Sample Isolation Valve solenoids on Units 1 and 2 and the Main Steam Isolation Valve limit switches on Unit 1. The above items have been reported to the NRC in LER Nos. 50-321/79-36, 50-366/79-41, and 50-321/79-37 respectively. These items will be replaced as stated in the LER's.

The detailed information requested by item three of Bulletin 79-01 is being compiled by the architect/engineer and the NSSS supplier. It is expected that the required information will be available by July 1, 1979.

A review of ASCO solenoids as identified in supplement IE Bulletin 79-01A has begun. The review is expected to be complete by July 1, 1979.

Should you have any questions, please contact my office.

Very truly yours,

E. W. Staffa
Manager of Quality Assurance

438
JAB/bg

xc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303
ATTN: Mr. James P. O'Reilly

326 341

①
7907190 355 Q
790235
OFFICIAL COPY