



LOCAL PDR

CENTRAL FILES  
PDR:HQ  
LPDR  
TIC  
NSIC

PUBLIC SERVICE COMPANY OF COLORADO

P. O. BOX 840 · DENVER, COLORADO 80201

C. K. MILLEN

SENIOR VICE PRESIDENT

May 22, 1979  
Fort St. Vrain  
Unit No. 1  
P-79108

Mr. Karl V. Seyfrit, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76012

Subject: I & E Bulletin 79-09

Dear Mr. Seyfrit:

It has been determined that GE Type AK-2 circuit breakers are not installed in safety related systems at the Fort St. Vrain plant.

We plan no further action on this matter.

Very truly yours,

C. K. Millen  
Senior Vice President

CKM:FMM:il

cc: U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement,  
Division of Reactor Operations Inspection  
Washington, D. C. 20555

400 360

(1)

7907190699