

PILGRIM NUCLEAR POWER STATION
RFD #1 ROCKY HILL ROAD
PLYMOUTH, MASSACHUSETTS 02360

July 20, 1979

BECO Ltr # 79-149

Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Licensee Event Report 79-025/01T-0

Docket Number 50-293
License DPR-35

Gentlemen:

The attached Licensee Event Report 79-025/01T-0, Primary Containment, is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.1.f. The Operations Review Committee has reviewed this event and classified it as a procedural inadequacy which could prevent the fulfillment of systems required to cope with accidents analysed in the FSAR.

If there are any questions on this subject, please contact us.

Respectfully submitted,



P. J. McGuire
Station Manager
Nuclear Operations

JMF/dmh

Enclosures: (3 copies)
LER

cc: Director (40 copies)
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

7907260667

(2)

454

288