



PILGRIM NUCLEAR POWER STATION
RFD # 1 ROCKY HILL ROAD
PLYMOUTH, MASSACHUSETTS 02360

July 19, 1979

BECo Letter #79-148

Director, Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Licensee Event Report - 79-022/01T-0

Docket Number 50-293

License DPR-35

Gentlemen:

The attached Licensee Event Report 79-022/01T-0, Pipe Supports, is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.1.h. The Operations Review Committee has reviewed this event and classified it as an error in the methods used for such analysis as described in the Safety Analysis Report.

If there are any questions on this subject, please contact us.

Respectfully submitted,

P. J. McGuire
Station Manager
Nuclear Operations

JMF/cf

Enclosures: (3 copies)

LER

cc: Director (40 copies)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

454 240

②

7907260 738 S