



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 27, 1979

1-079-13

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011

Subject: Arkansas Nuclear One-Unit 1  
Docket No. 50-313  
License No. DPR-51  
Reportable Occurrence Report  
Nos. 50-313/79-009 and  
50-313/79-010  
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.1 and 6.12.3.2, we have attached the subject reports concerning the tripping of the Reactor Building Hydrogen Purge Fan during surveillance testing (50-313/79-009) and the inadequately designed Hydraulic Shock Suppressors.

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:BI:gp

Attachments

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and  
Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, DC 20555

Mr. Norman M. Haller, Director  
Office of Management and  
Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, DC 20555

Mr. W. D. Johnson  
U. S. Nuclear Regulatory Comm.  
P. O. Box 2090  
Washington, DC 20555

435 025

6

7908020 449