

PAR



May 31, 1979

Serial No. 1-74
Docket No. 50-346
License No. NPF-3

JAMES S. GRANT

Vice President
Energy Supply
(419) 259-5232

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

This letter is in response to IE Bulletin Nos. 78-12, 78-12A and 78-12B as applicable to the Davis-Besse Nuclear Power Station Unit No. 1. Babcock & Wilcox (B&W) has provided the requested information in a report titled "Records Investigation Report Related to Off-Chemistry Welds in Material Surveillance Specimens and Response to Bulletin 78-12 and 12A Supplement" which is applicable to the Davis-Besse facility. Their March 13, 1979 submittal letter is included as Attachment A. In addition, to cover all welds as called for in the 78-12B, Item 2, Page 1, we are attaching a copy of B&W letter DB-79-45 dated May 24, 1979 (Attachment B) which covers those ferritic welds on Davis-Besse Unit 1 not covered in the Records Investigation Report.

Yours very truly,

J. S. Grant / ean

Attachments A and B

dh d/9

7908030610

440 105

04 1979