

Public Service Electric and Gas Company P.O. Box 168 Hancocks Bridge, New Jersey 08038

Salem Nuclear Generating Station

June 15, 1979

Mr. Boyce H. Grier  
Director of USNRC  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Sir:

REPORTABLE OCCURRENCE 79-46/01P  
SALEM NO. 1 UNIT LRR


This letter will serve to confirm our verbal report to Mr. Leif Norrholm, the Salem NRC Resident Inspector, at the Region I office on June 14, 1979, advising of a reportable occurrence in accordance with Technical Specification 6.9.1.8.

Radiographic inspection of our No. 13 steam generator feed nozzle to pipe weld revealed a linear indication approximately 5 inches in length.

Notification of this apparent indication has been made to Public Service Engineering and Construction Department requesting further evaluation and subsequent verification of this indication.

A detailed report will be submitted in the time period specified by the Technical Specifications.

Very truly yours,



H. J. Midura  
Manager - Salem Generating Station

AWK:lds

CC: General Manager - Electric Production  
Manager - Quality Assurance



311 133

①  
7907090 213 S