

1E MAIL

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

June 1, 1979

19 JUN 4 A 9:47

USNRC REGION II
ATLANTA, GEORGIA

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANTS A AND B - REPORTABLE DEFICIENCY - SPRAY POND
CENTRAL SUPPORT EARTHFILL MOISTURE CONTENT OUTSIDE ACCEPTABLE LIMITS
(NCR'S HNP-B11, HNP-B12)

Initial report of the subject reportable deficiency was made to Tom Burdette, NRC-OIE, Region II, on October 13, 1978. The first interim report was submitted to you on November 13, 1978. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we are enclosing the final report of the subject deficiency. If you have any questions regarding this matter, please call Tish Jenkins at FTS 854-2014.

Very truly yours,

J. E. Gilleland
J. E. Gilleland
Assistant Manager of Power

Enclosure

3019
S 1/1

310 086

7907090

(19)

388 S
Chers 395

790119

OFFICIAL CO