

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

0 1 1 1 L Q A D 1 2 0 0 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CON'T

0 1 REPORT SOURCE L 6 0 1 0 1 1 5 4 7 0 6 0 1 7 9 8 0 6 2 7 7 9 9
7 8 60 61 62 69 74 75 80
NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABILISTIC CONSEQUENCES (10)

0 2 | The drywell to suppression chamber vacuum breaker Division II alarm system breaker
0 3 | was found tripped and reported as a Non-Reportable Occurrence on April 10, 1979, and
0 4 | should be reclassified. At the time the breaker was found tripped, Division I alarm
0 5 | system was operable and the drywell to suppression chamber d/p was constant. The
0 6 | alarm system does not affect the operability of the vacuum breakers, thus the vacuum
0 7 | breaker system was at all times operable.

0	8											80		
7	8	9	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE				COMP. SUBCODE	VALVE SUBCODE		
C	9		S	A	E	A	C	K	T	B	R	K	A	Z
7	8	9	9	10	11	12	13	14	15	16	17	18	19	20
(17) LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.				
7		21		24		27		30		32				
1		7		0		2		L		0				
33		34		35		36		37		38				
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOW'N METHOD		HOUR		ATTACHMENT SUBMITTED				
X		Z		Z		Z		0		N				
18		19		20		21		22		23				
33		34		35		36		37		38				
NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER										
N		N		G										
24		25		26										
42		43		44										

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the breaker trip is unknown. A Division breaker trip is uncommon in that
1 1 there has not been a problem of tripping in the past. The Division II breaker was
1 2 reclosed on April 10, with no re-occurrence of the problem.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (1) 5 (2) E (28) 0 9 6 (29) NA (30) METHOD OF DISCOVERY (31) A (32) Operational Event (33) Z (34) Z (35) NA (36) NA

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION
1	7	0	0	NA

POOR ORIGINAL

PERSONNEL INJURIES											
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8		9		10		11		12	
1		2		3		4		5		6	
7		8									

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
Z (42) NA 478 1947907110445 S

[illegible]

NRC USE ONLY

NAME OF PREPARER

J. Vahrenwald

PHONE: 306 654-2241 Ext. 195